

USING GUIDE

NRBC

RUBBER BOOTS WITHOUT LINING

Highly impermeable to mustard gas
High mechanical resistance
Resistance to fuel oil
Sole resistant to contact heat (1 minute at 300°C)
Decontaminable

Criteria for assessment of the state of footwear :

Footwear should be assessed at regular intervals by inspection and should be replaced when any of the signs of wear identified below are found:

- Beginning of cracking affecting the upper material
- Abrasion of the upper material
- The upper shows areas with deformations, burns, fusions or bubbles
- The outsole shows cracks
- Upper/sole beginning of separation
- Cleat height in the flexing area lower than 1,5 mm

Care and Maintenance: Outer cleaning with soapy water. Storage sheltered from sun light or heat.

Obsolescence deadline: The footwear durability depends on the level of use and storage conditions. In any case it is necessary to replace the footwear at the latest 10 years after the date written on the outer sole.

ETCHE SECURITE
ZA Ordokia
64130 VIODOS ABENSE DE BAS
France
www.etchesecurite.com